



MIDDLETON

2500

Brown & Williamson

Tower

Louisville, Kentucky

40202

502.584.1135

502.501.0442 Fax

www.mmiddleton.com

April 18, 2006

Commissioner of Patents & Trademarks
P.O. Box 1450
Alexandria, VA 22313-1450

Re: United States Patent No. 6926162
Issued: Aug. 9, 2005
Inventor(s): Culley
For: Tamper Indication Band Arrestor

John F. Salazar
Direct Dial: (502) 625-2796
JSalazar@middleton.com

Dear Sir:

In proofreading the above-referenced United States Patent against the patent application text, it was noted that the following error requires correction:

Column 5, line 20, delete "finish bead 64" insert - - finish bead 61 - - ;

Column 5, line 39, delete "t₅" insert - - t₅ - -;

Column 6, line 19, delete "container neck 161" insert - - container neck 160 - -

At the present time, this error does not warrant a certificate of correction under 35 USC 254 and this letter is being forwarded in lieu thereof. Since this error is due to an Office mistake, no fee is due pursuant to 37 CFR 1.322. We would, therefore, appreciate and ask that the instant letter be placed in the file wrapper for the above-referenced United States Patent so as to become a permanent paper in the records.

Respectfully submitted,
MIDDLETON REUTLINGER

John F. Salazar, Esq.
Reg. No. 39,353